PMA Shades and Repairs

Erie Aviation, Inc.

Cockpit Roller Shade replacement screen!



Erie Aviation Repair Process

Airbus units are no longer repairable using OEM material! Solution: EAI's material!

When you send your unit in for repair, we will replace your current screen film with a much improved Grey screen film.



Amber Screen



Some of the Advantages:

Reduced Repair and Operating Costs • Reduced Glare Quick Turn Times • Reduce Pilot Fatigue Cooler Cockpit with up to 92% Heat Rejection **Better Reflective Properties**

Replace the screen film instead of buying a brand new roller shade!

only \$47.5

The following roller shade P/N's can be repaired using our film.

AIRBUS170-12180-9901-7011-100EAI-4011-990-AB170-12155-9901-7012-100EAI-4012-990L-AB170-12156-9901-7013-100EAI-4012-990R-AB170-14458-9901-2114-100GEAI-4114-990-B170-14459-9901-2112-100GEAI-4112-990-B170-14460-9901-2113-100GEAI-4113-990-B170-14461-9901-2111-100GEAI-4111-990-B170-14461-9901-2111-100GEAI-4111-990-B170-14461-9901-2111-100GEAI-4111-990-B170-14461-9901-2111-100GEAI-4311-990-BMBEMBRAER1-6312-300EAI-4312-990-EMB	AIRCRAFT	OEM P/N	ALT. P/N	EAI PMA
Interse <t< th=""><th rowspan="3">AIRBUS</th><th>170-12180-990</th><th>1-7011-100</th><th>EAI-4011-990-AB</th></t<>	AIRBUS	170-12180-990	1-7011-100	EAI-4011-990-AB
BOEING 170-14458-990 1-2114-100G EAI-4114-990-B 170-14459-990 1-2112-100G EAI-4112-990-B 170-14460-990 1-2113-100G EAI-4113-990-B 170-14461-990 1-2111-100G EAI-4111-990-B 170-14461-990 1-2111-100G EAI-4111-990-B 1-6311-300 EAI-4311-990-EMB		170-12155-990	1-7012-100	EAI-4012-990L-AB
BOEING 170-14459-990 1-2112-100G EAI-4112-990-B 170-14460-990 1-2113-100G EAI-4113-990-B 170-14461-990 1-2111-100G EAI-4111-990-B 170-14461-990 1-2111-100G EAI-4111-990-B EMBRAER 1-6311-300 EAI-4311-990-EMB		170-12156-990	1-7013-100	EAI-4012-990R-AB
BOEING 170-14460-990 1-2113-100G EAI-4113-990-B 170-14461-990 1-2111-100G EAI-4111-990-B 1-6311-300 EAI-4311-990-EMB	BOEING	170-14458-990	1-2114-100G	EAI-4114-990-B
170-14460-990 1-2113-100G EAI-4113-990-B 170-14461-990 1-2111-100G EAI-4111-990-B 1-6311-300 EAI-4311-990-EMB		170-14459-990	1-2112-100G	EAI-4112-990-B
EMBRAER 1-6311-300 EAI-4311-990-EMB		170-14460-990	1-2113-100G	EAI-4113-990-B
EMBRAER		170-14461-990	1-2111-100G	EAI-4111-990-B
	EMBRAER	1-6311-300		EAI-4311-990-EMB
		1-6312-300		EAI-4312-990-EMB

Basic Repairt

Labor, Screen, Tape, if needed Pull Bar, Felt, Hook & End Caps

We also offer a Metal Cover[†] replacing the OEM composite cover. tadditional parts outside of the basic repair not included **price subject to change*

Erie Aviation, Inc. 1607 Asbury Road • Erie, PA 16505 www.erieaviation.com

Phone: 814-838-8934 • Fax: 814-833-3673 sales@erieaviation.com

2024.03